

OK ROTT.
04/9

MAGNA
Cod. For. 91015057
11 FEB. 2025
"Ricevuto con riserva e verifica"
Firma
Leggibile

~~504388827~~

rexroth
A Bosch Company

Pagina 1/ 2

Bosch Rexroth AG, D-97813 Lohr

Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO BA
ITALIEN

5014081073

Bolla di consegna

Luogo di sped.	Bosch Rexroth AG Fornsbacherstrasse 92 71540 Murrhardt
N° documento/Data:	8029995114 / 03.02.2025
N° ordine/Data:	1015679595 / 27.01.2025
Ordine di:	Elena Manenti
V. riferimento:	300968746
Cod. fornitore:	97057801
Cod. cliente:	6126162
Vs. p. IVA:	IT00744460155
Contatto:	Fr. Lauber
Tel.:	07192-22-413



Committente:
Bosch Rexroth S.p.A.
S.S. Padana Superiore 11,41
I-20063 CERNUSCO SUL NAVIGLIO MI

Tipo di ordine: riparazione
N° colli: 1
IMBALLAGGIO KT KARTON C11 1 260x210x120 MM 1,130 KG

Spedizioniere: TNT Express

Condizioni di fornitura: DAP (INCOTERMS 2020) per quanto riguarda il trasfer. del rischio Modugno, incluse spese di imballaggio

Alla pagina seguente troverete ulteriori informazioni sull'etichettatura ambientale degli imballaggi Bosch Rexroth ai sensi del D.Lgs. 116/2020: www.boschrexroth.it/packaging

Volume: 4,140 CDM

Pos.	Materiale/Definizione	Qtà	Peso
010300	0608820111 SENSORE DI MISURA 2DMC012 SZ2	1 PZ	1,000 KG
	HU:		1035071081
	N° di serie:	(760000003)	
	N° d'ordine WE/Posiz:		4500701522
	N° d'ordine AG/Pos.:		4510447085
	Data d'ordine AG:		08.01.2025
	Ordine di:		Elena Manenti
	Procedure no.:	000941389967	

31155344
RDA 16262927

ELO-MO3356

N° merci statistico.: 90318080

Firmensitz/Headquarters: Stuttgart; Registrierung/Registration: Amtsgericht Stuttgart HRB 23192
Vorstand/Executive Board: Dr. Steffen Haack (Vorsitzender/President),
Roland Bittenauer; Thomas Fechner; Holger von Hebel; Reinhard Schäfer
Vorsitzende des Aufsichtsrats/Chairman of the Supervisory Board:
Dr. Tanja Rückert

Bolla di consegna

Bosch Rexroth AG, D-97813 Lohr

N° documento/Data: 8029995114 /
03.02.2025

Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO BA
ITALIEN

Pos.	Materiale/Definizione	Qtà	Peso
	Paese produttore:		SI

Packing list

=====

Shipping point
Bosch Rexroth AG
Fornsbacherstrasse 92
71540 Murrhardt

Page: 1
Package no.: 1035071081
Order no.: 1015679595
Delivery note no.: 8029995114
Customer order no.: 4510447085

Consignee
Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO BA
ITALIEN

Item	Material	Description	Qty
10300	0608820111	SENSORE DI MISURA 2DMC012 SZ2	1,00 ST
	Tariff no.:	90318080/SI	
1		net weight 1,00 gross weight	1,13
		dimensions 260X210X120 MM	

Bosch Rexroth AG - D-97813 Lohr

Result Report / 03.02.2025

Bosch Rexroth S.p.A.
S.S. Padana Superiore 11,41
20063 CERNUSCO SUL NAVIGLIO MI
ITALIEN

Serv.not./date: 941389967 /23.01.2025
Number/Pos.: 1015679595 /010000
Order no./date: 4510447085 /08.01.2025
Customer no: 6103383
Referenz-Nr.:
Analyzing dep.: DC-IA/SVF
Processed by: Fr. Lauber
Tel: 07192-22-413
Fax: 07192-22-164
Email: repair.jt@boschrexroth.de

Page 1 / 3

We hereby notify you of the finding with regard to the following items:

Quant.	Material Orig. material code addl. customer info	Description FD	Serial no.
0000001	0608820111	MESSWERTGEBER 760	2DMC012 SZ2 760000003

Customer material no.:

Order reason: IA-elec.drivesrepairing contr.-repairing in-house
Order description:
Customer report: no function
Report description: Redundanzfehler
Delivery condition : Visually OK

Subassembly: 3608877518 TORSIONSMESSWELLE BG2 12NM
Component position: TOPF NEU
Fault location: Torsion Bar
Type of fault: Loose

The pot from the torsion shaft was loose, this caused the error "zero point error". The defective torsion shaft and both ball bearings have been exchanged. The measurement transducer was tested and new adjusted.

Calculation type: Repair

Result report / 03.02.2025

Serv.not./date: 941389967 /23.01.2025
Order no./Pos.: 1015679595 /010000

Page 2 / 3

The following standardized processes were carried out in the course of the requested service:

Testing:

- Functional test according to specification including preparation of a test report

Maintenance:

- Input inspection with visual inspection for mechanical damage
- Disassembly Measurement transducer
- Cleaning of all parts
- Replacement of the defined wear parts
- Assembly Measurement transducer
- Function test according to specification including preparation of a test report

Repair:

The repair includes a warranty of 12 months on replaced parts.

- Input inspection with visual inspection for mechanical damage as well as input function test
- Reproduction of the fault indication, as far as information from the customer is available
- Disassembly Measurement transducer
- Cleaning of all parts
- Replacement of defective parts
- Assembly Measurement transducer
- Function test according to specification including preparation of a test report

Product overhaul:

The product overhaul includes the overhaul of all parts and components with implementation of technical updates incl. 24 months warranty on the complete product.

- Input inspection with visual inspection for mechanical damage as well as input function test
- Reproduction of the error indication, as far as information from the customer is available
- Disassembly Measurement transducer
- Cleaning of all parts
- Replacement of defective parts, defined wear parts as well as incorporation of possible further product developments
- Assembly Measurement transducer
- Functional test according to specification including preparation of a test report

Incoming goods: 27.01.2025
Completion of repair procedure: 03.02.2025

Result report / 03.02.2025

Serv.not./date: 941389967 /23.01.2025
Order no./Pos.: 1015679595 /010000

Page 3 / 3

Yours sincerely

Bosch Rexroth AG