rexroth
A Bosch Company

Bosch Rexroth AG - D-97813 Lohr

Bosch Rexroth Sp. z o.o.
ul. Jutrzenki 102/104
02-230 WARSZAWA
POLEN

Result Report / 10.03.2025

Serv.not./date:	941396009 /06.03.2025
Number/Pos.:	1015751076 /010000
Order no./date:	claim 300978528 /28.02.2025
Customer no:	6020823
Referenz-Nr.:	
Analyzing dep.:	DC-IA/SVF
Processed by:	Michael Rost
Tel:	07192-22-142
Fax:	07192-22-164

Email: repair.jt@boschrexroth.de

ELO-M 03422
GARANZIA

We hereby notify you of the finding with regard to the following items:

Quant.	Material Orig. material code addl. customer info	Description FD	Serial no.
0000001	0608830254	EINKANAL-STEUERUNG CS351S-D 339	339110109

Customer material no.:

Order reason: IA-elec.drivesrepairing contr.-repairing in-house
Order description:
Customer report: no function
Report description: Error 1219

Fault location: Compact tightening system
Type of fault: Not fully turned

The CS Box electronics had an internal loose contact. The defective Part was replaced. A complete functional test and an endurance test was carried out. A backup was created before the check, this was restored after the check.

Calculation type: Warranty

Result report / 10.03.2025

Serv.not./date: 941396009 /06.03.2025
Order no./Pos.: 1015751076 /010000

The following standardized processes were carried out:

- Input inspection with visual inspection for mechanical damage as well as input function test
- Reproduction of the fault indication, as far as information from the customer is available
- Disassembly compact system 350
- Cleaning of all parts
- Replacement of defective parts as well as incorporation of possible further product developments
- Assembly compact system 350
- Safety and function test with thermal endurance run according to specification

In the course of repair and maintenance, the software version is installed according to the version delivered to the service workshop, including the latest available service pack (SP). If no software version can be read out, the software version with the service pack (SP) will be installed according to the parts list of the product valid for the repair. Unless otherwise requested by the customer.

Incoming goods: 06.03.2025
Completion of repair procedure: 10.03.2025

Yours sincerely

Bosch Rexroth AG