rexroth
A Bosch Company

413517

Bosch Rexroth AG, D-97813 Lohr

Bolla di consegna

Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO, BA
ITALIEN

MAGNA
Cod. Fr. 9161507
28 MAG. 2024
"Ricevuto con riserva e verifica"
Firma
Leggibile

Luogo di sped.	Bosch Rexroth AG Bgm. - Dr. - Nebel - Str. 2 97816 Lohr
N° documento/Data:	**8029229098 / 22.05.2024**
N° ordine/Data:	1015268972 / 15.05.2024
Ordine di:	Massimo Cesati
Cod. fornitore:	368432
Cod. cliente:	6126162
Vs. p. IVA:	IT00744460155
Contatto:	Daniel Roth
Tel.:	+49(9352)18-4808
Fax:	+49(9352)18-4994

Committente:
Bosch Rexroth S.p.A.
S.S. Padana Superiore 11, 41
I-20063 CERNUSCO SUL NAVIGLIO MI

Tipo di ordine: riparazione
N° colli: 1
CARTONE OND.PIEGH. 390X205X160-GR. 0 1 402x220x195 MM HU: 342515551128221009

Spedizioniere: UPS Süd/Ostdeutschland Distrikt

Condizioni di fornitura: DAP (INCOTERMS 2020) per quanto riguarda il trasfer. del rischio benannte Lieferadresse, incluse spese di imballaggio

Alla pagina seguente troverete ulteriori informazioni sull'etichettatura ambientale degli imballaggi Bosch Rexroth ai sensi del D.Lgs. 116/2020: www.boschrexroth.it/packaging

386481

Peso lordo complessivo: 1,250 KG
Peso netto complessivo: 0,850 KG

NOTE:

PLEASE FIND THE REPAIR-REPORT(S) FOR THE REPAIRITEMS TOGETHER WITH THE DELIVERY-NOTE IN THE CORRESPONDING DOCUMENT-BAG!

50134758604

Pos.	Materiale/Definizione	Qtà		Peso
000103	R911297009	1	PZ	0,850 KG
	UNITA DI COMANDO CSH01.1C-SE-EN2-NNN-NNN-S1-S-NN-FW			
	N° di serie:	(CSH011-72926)		
	N° d´ordine WE/Posiz:	4500686816 date 07.05.2024		
	N° d`ordine AG/Pos.:	4510066427		

rexroth
A Bosch Company

Bolla di consegna

Bosch Rexroth AG, D-97813 Lohr

N° documento/Data: 8029229098 / 22.05.2024

Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO BA
ITALIEN

Pos.	Materiale/Definizione	Qtà	Peso
	Data d`ordine AG:	15.05.2024	
	Ordine di:	Massimo Cesati	
	N° merci statistico.:	85049090	
	Paese produttore:	DE	

This spare part or replacement device is only intended for use in and systems already in operation.

The technical status at the time of placing the machine or system on the market applies.

Observe the directives and standards applicable to the product and the application as well as local regulations at the place of operation.

It is absolutely necesseary to check each shipment immediately upon receipt. All transportation damages must be documentated at once on the carriers freight papers. Concealed damages must be reported within 5 days after receipt of the merchandise.

Bosch Rexroth .Electric Drives and Controls. offre un supporto Service professionale con presenza in quasi tutti i paesi del mondo. Chiediamo il Vostro aiuto e cooperazione per far modo che il nostro supporto Service possa essere ottimizzato ed adeguato alle necessitá dei nostri clienti in tutto il mondo. Vi preghiamo di informarci al seguente indirizzo www.boschrexroth.com/endverbleibsmeldung dove e quali Vostre macchine, dotate dei nostri componenti e sistemi nel settore degli azionamenti elettrici e controlli, vengono utilizzate nei diversi paesi del mondo.

Please note that from 1 April 2015, orders under 100 Euro becomes a minimum quantity surcharge in the amount of 30 Euro will be charged.
Per evitare tale costo, utilizzate le possibilità offerte dall Rexroth Store all'indirizzo https://store.boschrexroth.com/?cclcl=de_DE.

rexroth
A Bosch Company

Bosch Rexroth AG - D-97813 Lohr

Bosch Rexroth S.p.A.
S.S. Padana Superiore 11, 41
20063 CERNUSCO SUL NAVIGLIO MI
ITALIEN

Result Report / 23.05.2024

Serv.not./date:	941356456 /14.05.2024
Number/Pos.:	1015268972 /000103
Order no./date:	4510066427 /15.05.2024
Customer no:	6644206
Order:	SDD
Referenz-Nr.:	
Analyzing dep.:	DC-AE/SVC432
Processed by:	Daniel Roth
Tel:	+49(9352)18-4808
Fax:	+49(9352)18-4994

Email: daniel.roth@boschrexroth.de

We hereby notify you of the finding with regard to the following items:

Quant.	Material Orig. material code addl. customer info	Description FD	Serial no.
0000001	R911297009	CSH01.1C-SE-EN2-NNN-NNN-S1-S-N 22.10.2008 CSH011-72926	

Customer material no.:

Order reason: IA-elec.drivesrepairing and product overhaul contr.-repairing in-house
Order description: REMAN
Customer report: without fault note
Report description: without error description
Delivery condition : Visually OK

Type of fault: conforming to specification
no fault discoverable
PFM02.1-016-NW (no firmware) was included in the repair
We carried out a product overhaul with the above mentioned component. During the product overhaul all wearing parts were renewed. The product is technically as good as new.

Calculation type: Repair

Result report / 23.05.2024

Serv.not./date: 941356456 /14.05.2024
Order no./Pos.: 1015268972 /000103

The following standardized repair process has been carried out

- Reproduction of the error note (when available) by visual inspection and functioning test under load
- Compare the current equipment configuration with the delivery configuration and write down any deviations
- Exchange of defective components
- Implementation of hardware modifications
- Firmware release update
- Check and update the data of the controller
- Check the protective monitoring
- Load test in the control unit with the respective motor generation
- Heat endurance test lasting several hours
- Reset the application parameters to specified basic parameters
- Documentation and archiving of all repair and quality relevant data
- Documentation of the repair week on the type plate

During a product overhaul (PÜ), additionally all electronic and mechanic wearing parts have been replaced by new parts.

Finally, the product has been marked with a "PÜ-label" (product overhaul) near the type plate of the unit in order to mark the revised units.

Incoming goods: 14.05.2024
Completion of repair procedure: 22.05.2024