

129615


DOCUMENTO DI TRASPORTO (D.d.t.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

Numero: **40001508**
 Data: **24.09.2020**
 Documento materiale: **5010677690**
 Ordine di acquisto: **5500043380**

Creato da: **N.MIGLIETTA***Destinatario*

Musashi Hungary Manufacturing
Ercseny ut 1
H-2451 ERCSI

Partita iva:

Luogo di destinazione

Musashi Hungary Manufacturing
Ercseny ut 1
H-2451 ERCSI

Partita iva:

922 EM ord. acq. Storno				Trasporto a mezzo vettore			
Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.	
001	6	PZ	2510073215	Scatola differenziale pre	22,800	KG	
 Magna PT S.p.A. Via dei Ciclamini, 4 70026 MODUGNO (BA) C. F. e P. IVA 04886850728							
Aspetto				Nota			
CARTONE				I. R. 2-109466 DHL1587863664			
Colli		Peso lordo		Tipo trasporto		ID Trasporto	Incoterms
1 PZ		31,000 KG					
Vettore				Data e ora del ritiro		Firme	
DHL EXPRESS				25.09.2020 08:29:51			
						Conducente	
						Destinatario	



Quality Inspection Report

Inspection report No.: 200000109466
 Receipt No.: 5010616998
 Deliver note: 80002681

Date of inspection: 10.09.2020
 Date of reception: 04.09.2020

Supplier

Musashi Hungary Manufacturing Ltd.
Ercseny ut 1
2451 Ercsi
Hungary

Quality Contact

Name: Ruggiero Doronzo
 Phone: _____
 E-Mail: Ruggiero.Doronzo@magna.com

Material

Material-No.: 2510073215
 Description: Differential Housing Pre Asm

Delivery Qty: 840
 Tax ID number: HU11979463

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
 We would like to request you to take according containment actions and to avoid repetitive failures in future.
 In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

1 PEDANA

Failure description:

Distance N8 hole undersized

Quality Notification Origin: Assembly line
 Defect: Distance N8 undersized (see Mr. Attila's mail)
 we have blocked the batch 80002681 (840parts) and batch 80002691 (360parts)
 All batches before 80002701 must be sorting.
 Containment Actions must be implemented and reported to Magna PT Bari Incoming Inspection in written form within 24 hours.

*80x60x50 mm
31 kg*

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to following email: getrag.holine.supplier@magna.com

Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
 In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 446
 Redelivered quantity: 440

Best regards

Ruggiero Doronzo

Magna PT S.p.A.
 a socio unico
 Via dei Ciclamini 4
 I-70026 Modugno (Bari)
 Tel. 080 - 5 85 81 11
 Fax. 080 - 5 85 82 04
 Subject to the activity of the direction
 and coordination of
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
 i.v.R. Imprese di Bari
 C.F. e P.IVA 04886850728
 REA 339886
 www.magna.com

EUR: BNL-Banca Nazionale del Lavoro
 SpA
 IBAN code EUR: IT94 V010 0504 0000
 0000 0007 855
 BIC code: BNLIITRR 6560 12
 USD: Bank of America N.A.
 IBAN code USD: GB64 BOFA 1650
 5071 1710 20
 BIC code: BOFAGB22

Ref 5010616998



Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

MUSASHI HUNGARY MANUFACTURING
//
ERCSENY UT 1

2451 ERCSENY
Hungary
+3625551800

Dettagli Spedizione

Data Spedizione: 2020-09-25
Numero Spedizione: 1587863664
Tipo Servizio: EXPRESSWORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 31,00kg
Volumetrico: 48,00kg
Tassabile: 48,00kg
Valore assicurato:
Condizioni commerciali:

Info internazionali

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Tuesday, 29 Sep, 2020
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 113812703
Codice per oneri e tasse:
Charge Breakdown: 209,89 EUR

Servizi speciali: Supplemento Carburante/
Emergency Situation

Info riferimento

Riferimento: I.R.2 -109466
Numero di ritiro:

Contenuto

RICAMBI