



129204

DOCUMENTO DI TRASPORTO (D.d.t.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

**Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO**

Partita iva: IT04886850728

Numero: **40001141**
Data: **05.08.2020**
Documento materiale: **5010567398**
Ordine di acquisto: **5500039643**
Creato da: **ANTOMOSC**

Destinatario

**Robert Bosch GmbH
Robert Bosch ut 1
H-3000 HATVAN**

Partita iva:

Luogo di destinazione

**Robert Bosch GmbH
Robert Bosch ut 1
H-3000 HATVAN**

Partita iva:

922	EM ord. acq. Storno	Trasporto a mezzo vettore
------------	----------------------------	----------------------------------

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	1	PZ	2510261630	Centralina Daimler	1,030	KG

MAGNA
Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO (BA)
C. F. e P. IVA 04886850728

Aspetto		Nota			
CARTONE		I.R. 2-109124 DHL 5716796536			
Colli	Peso lordo	Tipo trasporto	ID Trasporto	Incoterms	
1 PZ	3,000 KG				
Vettore		Data e ora del ritiro		Firme	
DHL EXPRESS		06.08.2020 09:29:29			
				Conducente	
				Destinatario	



Quality Inspection Report

Inspection report No.: 200000109124
 Receipt No.: 5010255355
 Deliver note: 5851562

Date of inspection: 04.08.2020
 Date of reception: 14.03.2020

Supplier

Robert Bosch GmbH
 Robert Bosch ut 1
 3000 Hatvan
 Hungary

Quality Contact

Name: Francesco Giovannello
 Phone:
 E-Mail: Franco.Giovannello@magna.com

Material

Material-No.: 2510261630
 Description: TCU Daimler

Delivery Qty: 640
 Tax ID number: HU26951542

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits. We would like to request you to take according containment actions and to avoid repetitive failures in future. In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

due 5010567398

Failure description:

No communication

Quality Notification Origin: Customer Complain (Plant)
 Variant: 251/17.06 - Daimler

Complain Number: 176403
 Transmission serial: 20311457

Part Number: 2510261630
 Quantity Affected: 1 Part (Partial result)

Defect: No communication
 KM: 0 (Plant)
 MAM DATA MATRIX: 200225_91024089_0619655_2510261630_a

2693

5010261630

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to following email: getrag_hotline_supplier@magna.com

Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com. In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 1
 Redelivered quantity: 1

Best regards

Francesco Giovannello

Magna PT S.p.A.
 a socio unico
 Via dei Ciclamini 4
 I-70026 Modugno (Bari)
 Tel. 080 - 5 85 81 11
 Fax. 080 - 5 85 82 04
 Subject to the activity of the direction and coordination of
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
 i.v.R. Imprese di Bari
 C.F. e P.IVA 04886850728
 REA 339886
 www.magna.com

EUR: BNL-Banca Nazionale del Lavoro SpA
 IBAN code EUR: IT94 V010 0504 0000 0000 0007 855
 BIC code: BNLIITRR 6560 12
 USD: Bank of America N.A.
 IBAN code USD: GB64 BOFA 1650 5071 1710 20
 BIC code: BOFAGB22



Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

Robert Bosch
Robert Bosch
Robert Bosch ut 1

3000 HATVAN
Hungary
+390805858665

Dettagli Spedizione

Info Internazionali

Data Spedizione: 2020-08-06
Numero Spedizione: 5716796536
Tipo Servizio: EXPRESS WORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 3,00Kg
Volumetrico: 2,00kg
Tassabile: 3,00kg
Valore assicurato:
Condizioni commerciali:

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Monday, 10 Aug, 2020
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 113812703
Codice per oneri e tasse:
Charge Breakdown: 34,14 EUR

Servizi speciali: Supplemento Carburante/
Emergency Situation

Info riferimento

Riferimento: I.R. 2-109124
Numero di ritiro:

Contenuto

RICAMBI