

**DOCUMENTO DI TRASPORTO (D. d. t.)**

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

**Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO**

Partita iva: IT04886850728

Numero: **40000719**
Data: **11.06.2020**
Documento materiale: **5010403208**
Ordine di acquisto: **5500039712**Creato da: **ANTOMOSC**

Destinatario

**Robert Bosch GmbH
Robert Bosch ut 1
H-3000 HATVAN**

Partita iva:

Luogo di destinazione

**Robert Bosch GmbH
Robert Bosch ut 1
H-3000 HATVAN**

Partita iva:

106336

922	EM ord. acq. Storno	Trasporto a mezzo vettore
------------	----------------------------	----------------------------------

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	1	PZ	2510261400	Centralina RSA com	1,017	KG

Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO (BA)
C. F. e P. IVA 04886850728

Aspetto		Nota			
CARTONE		i.r. -108498 dhl 5663272252			
Colli	Peso lordo	Tipo trasporto	ID Trasporto	Incoterms	
1 PZ	1,300 KG				
Vettore		Data e ora del ritiro		Firma	
DHL EXPRESS		12.06.2020 08:44:32			
				Conducente	
				Destinatario	



Quality Inspection Report

Inspection report No.: 200000108498
Receipt No.: 5009649363
Deliver note: 3508696

Date of inspection: 10.06.2020
Date of reception: 06.09.2019

Supplier

Robert Bosch GmbH
Robert Bosch ut 1
3000 | Hatvan
Hungary

Quality Contact

Name: Francesco Giovannello
Phone: _____
E-Mail: Franco.Giovannello@magna.com

Material

Material-No.: 2510261400
Description: TCU RSA cpl

Delivery Qty: 640
Tax ID number: HU26951542

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
We would like to request you to take according containment actions and to avoid repetitive failures in future.
In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

*1 CARTONE
2,3 kg*

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

50x20x5cm

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

24.06.2020

Failure description:

No communication

Quality Notification Origin: Customer Complain (Plant)
Variant: 251/24.04-010 - Renault

Complain Number: 176132
Transmission serial: BRJ1C08

Part Number: 2510261400
Quantity Affected: 1 Part (Partial result)

Defect: No communication
KM: 0 (Plant)
MAM DATA MATRIX: 91024089_0512279_190810_2510261400_

5010403208

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to following email: getrag.hotline.supplier@magna.com

Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 1
Redelivered quantity: 1

Best regards

Francesco Giovannello

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax. 080 - 5 85 82 04
Subject to the activity of the direction
and coordination of
Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
i.v.R. Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del Lavoro
SpA
IBAN code EUR: IT94 V010 0504 0000
0000 0007 855
BIC code: BNLITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650
5071 1710 20
BIC code: BOFAGB22



Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

Robert Bosch
Robert Bosch
Robert Bosch ut 1

3000 HATVAN
Hungary
+390805858669

Dettagli Spedizione

Data Spedizione: 2020-06-12
Numero Spedizione: 5663272252
Tipo Servizio: EXPRESS-WORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 1,30kg
Volumetrico: 1,00kg
Tassabile: 1,50kg
Valore assicurato:
Condizioni commerciali:

Info internazionali

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Tuesday, 16 Jun, 2020
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 113812703
Codice per oneri e tasse:
Charge Breakdown: 21,29 EUR

Servizi speciali: Supplemento Carburante/
Emergency Situation

Info riferimento

Riferimento: I.R. 2-108488
Numero di ritiro:

Contenuto

ricambi