130562

MAGNA

DOCUMENTO DI TRASPORTO (D.d.t.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Numero:	40001796
Data:	16.10.2020
Documento materiale:	5010745149
Ordine di acquisto:	5500039712
Creato da:	ANTOMOSC

Cedente

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

Destinatario

Robert Bosch GmbH
Robert Bosch ut 1
H-3000 HATVAN

Partita iva:

Luogo di destinazione

Robert Bosch GmbH
Robert Bosch ut 1
H-3000 HATVAN

Partita iva:

922 EM ord. acq. Storno	Trasporto a mezzo vettore

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	1	PZ	2510261400	Centralina RSA com	0,980	KG

MAGNA
Magna PT S.p.A.
Via dei Ciclamini, 4
70026 MODUGNO (BA)
C. F. e P. IVA 04886850728

Aspetto	Nota
CARTONE	I.R. 2-109887 DHL2984341334

Colli	Peso lordo	Tipo trasporto	ID Trasporto	Incoterms
1 PZ	1,400 KG			

Vettore	Data e ora del ritiro	Firme
DHL EXPRESS	20.10.2020 11:52:40	
		Conducente
		Destinatario

Quality Inspection Report

MAGNA

Inspection report No.: 200000109887
Receipt No.: 5010303131
Deliver note: 5899450

Date of inspection: 15.10.2020
Date of reception: 22.04.2020

Supplier

Robert Bosch GmbH
Robert Bosch ut 1
3000 Hatvan
Hungary

Quality Contact

Name:
Phone:
E-Mail:

Material

Material-No.: 2510261400
Description: TCU RSA cpl

Delivery Qty: 640
Tax ID number: HU26951542

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
We would like to request you to take according containment actions and to avaoid repetitive failures in future.
In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

1 CARTONE

Failure description:

Quality Notification Origin: Customer Complain
Variant: Renault

Complain Number: 1'76785
Transmission serial: BSE2DA6
Vin: VF1RFE0016542486

Part Number: 2510261400
Quantity Affected: 1 Part (Partial result)

Defect:Dtc1945-92
Info: Clutch cooling motor phase performance or incorrect operation

KM: 2.342
MAM DATA MATRIX: 91024089.7025263.200308.2510261400_

50 X 20 X 5 cm
1,4 Kg
Mod.
5010745149

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to
following email: getrag.hotline.supplier@magna.com
Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 1
Redelivered quantity: 1

Best regards

0

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax. 080 - 5 85 82 04
Subject to the activity of the direction
and coordination of
Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
i.v.R.Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del
Lavoro SpA
IBAN code EUR: IT94 V010 0504 0000
0000 0007 855
BIC code: BNLIITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650
5071 1710 20
BIC code: BOFAGB22

Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

Robert Bosch
Robert Bosch
Robert Bosch ut 1

3000 HATVAN
Hungary
+390805858669

Dettagli Spedizione

Data Spedizione:	2020-10-20
Numero Spedizione:	2984341334
Tipo Servizio:	EXPRESS WORLDWIDE
Tipo Imballaggio:	My Own Package
Numero Colli:	2
Peso Totale:	2,80kg
Volumetrico:	2,00kg
Tassabile:	3,00kg
Valore assicurato:	
Condizioni commerciali:	

Info internazionali

Valore dichiarato:	
Codice per oneri e tasse:	
Stato tassabile:	Non-Dutiable
Data di consegna stimata:	Thursday, 22 Oct, 2020
Codice promozionale:	

Info di pagamento

Tipo pagamento:	DHL Account Number
Codice pagante:	113812703
Codice per oneri e tasse:	
Charge Breakdown:	34,45 EUR

Servizi speciali: Supplemento Carburante/ Situazione di emergenza

Info riferimento

Riferimento:	I.R. 2-109887-109884
Numero di ritiro:	

Contenuto

RICAMBI

2019 © Deutsche Post AG - All rights reserved