



Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

Seissenschmidt GmbH
JENS BIEGERT
Daimlerstrasse 11

58840 Plettenberg Nordrhein-Westfalen
Germany
+4923919150

159463

Dettagli Spedizione

Data Spedizione: 2020-12-15
Numero Spedizione: 8010541836
Tipo Servizio: EXPRESS WORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 0,50kg
Volumetrico: 0,40kg
Tassabile: 0,50kg
Valore assicurato:
Condizioni commerciali:

Info internazionali

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Thursday, 17 Dec, 2020
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 113812703
Codice per oneri e tasse:
Charge Breakdown: 13,11 EUR

Servizi speciali: Supplemento Carburante/
Situazione di emergenza

Info riferimento

Riferimento: I.R. 2-110594
Numero di ritiro:

Contenuto

RICAMBI

**Cedente**

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

DOCUMENTO DI TRASPORTO (D.d.T.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Numero: **40002514**
Data: **14.12.2020**
Documento materiale: **5010911401**
Ordine di acquisto: **5500039158**

Creato da: **N.MIGLIETTA**

Destinatario

Seissenschmidt GmbH
Daimlerstraße 11
D-58840 PLETTENBERG
GERMANIA

Partita iva: DE123840478

Luogo di destinazione

Seissenschmidt GmbH
Daimlerstraße 11
D-58840 PLETTENBERG
GERMANIA

Partita iva: DE123840478

922 EM ord. acq. Storno				Trasporto a mezzo vettore	
Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto U.M.
001	1	PZ	2511109290	Ruota dentata libera 6.M.	0,670 KG
 Magna PT S.p.A. Via dei Ciclamini, 4 70026 MODUGNO (BA) C.F. e P. IVA 04886850728					
Aspetto			Nota		
CARTONE			I.R. 2-110594 DHL 8010541836		
Colli	Peso lordo		Tipo trasporto	ID Trasporto	Incoterms
1 PZ	0,500 KG				
Vettore			Data e ora del ritiro		Firma
DHL EXPRESS			15.12.2020 08:36:55		
					Conducente
					Destinatario

Supplier Seissenschmidt GmbH Precision Components Daimlerstraße 11 D-58840 PLETTENBERG GERMANIA	<table border="1"> <tr> <th colspan="2">Advanced information for the supplier</th> </tr> <tr> <td>Inspection Report No./ created:</td> <td>200000110594 / 09.12.2020</td> </tr> <tr> <td>Goods receipt No.:</td> <td>5010873132</td> </tr> <tr> <td>Delivery No.:</td> <td>80794903</td> </tr> <tr> <td>Goods receipt Date:</td> <td>30.11.2020</td> </tr> <tr> <td>Part description</td> <td>Part-No.</td> </tr> <tr> <td>Speed Gear 6th raw part</td> <td>2511109290</td> </tr> <tr> <td>Quantity:</td> <td>5.400</td> </tr> <tr> <td>VAT No.:</td> <td>IT04886850728</td> </tr> </table>	Advanced information for the supplier		Inspection Report No./ created:	200000110594 / 09.12.2020	Goods receipt No.:	5010873132	Delivery No.:	80794903	Goods receipt Date:	30.11.2020	Part description	Part-No.	Speed Gear 6th raw part	2511109290	Quantity:	5.400	VAT No.:	IT04886850728
Advanced information for the supplier																			
Inspection Report No./ created:	200000110594 / 09.12.2020																		
Goods receipt No.:	5010873132																		
Delivery No.:	80794903																		
Goods receipt Date:	30.11.2020																		
Part description	Part-No.																		
Speed Gear 6th raw part	2511109290																		
Quantity:	5.400																		
VAT No.:	IT04886850728																		
During inspection of the above mentioned parts we found the below listed defects. We expect you to take correctiv actions to prevent such problems in the future. Another inspection report will be issued in case of further defects found on the same parts. The payment of the goods after discovering the deficiencies by GETRAG is not considered as an acknowledgement of the goods as duly. You are requested to send a written response (8D-Report) to department B/WLQ4 until 99.99.9999.																			
Defect description: lack material in internald diameter Quality Notification Origin: Reject Line Part Number: 2511109290 DLfect: lack material in internal diameter Cast: 624374 Quantity: 1pz QN Origin: RL Line Scrap Disturb Index: 2 2-High																			
Inspected quantity: 1 Return delivery quantity: 1																			
<table border="0"> <tr> <td>Quality contact person:</td> <td>Logistic contact person:</td> </tr> <tr> <td>Tester: Francesco Giovanniello</td> <td>Logistics:</td> </tr> <tr> <td>Telephone:</td> <td>Telephone:</td> </tr> <tr> <td>E-Mail: Franco.Giovanniello@magna.com</td> <td>E-Mail:</td> </tr> </table>		Quality contact person:	Logistic contact person:	Tester: Francesco Giovanniello	Logistics:	Telephone:	Telephone:	E-Mail: Franco.Giovanniello@magna.com	E-Mail:										
Quality contact person:	Logistic contact person:																		
Tester: Francesco Giovanniello	Logistics:																		
Telephone:	Telephone:																		
E-Mail: Franco.Giovanniello@magna.com	E-Mail:																		
Charges for the defective or rejected parts will be made seperately under the above mentioned number. CONTROL PLAN HAS TO BE REVIEW? YES NO With best regards Key 0,500 20x10 x10 Reg 501094401																			

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax 080 - 5 85 82 04

Cap.Soc.: EUR 25.850.000,00
i.v.R.Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del Lavoro SpA
IBAN code EUR: IT94 V010 0504 0000 0000 0007 855
BIC code: BNLIITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650 5071 1710 20
BIC code: BOFAGB22

Soggetta ad attività di direzione e coordinamento di Magna Powertrain GmbH
Subject to the activity of the direction and coordination of Magna Powertrain GmbH