

**DOCUMENTO DI TRASPORTO (D.d.t.)**

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

*Cedente***Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO**

Partita iva: IT04886850728

Numero: **40002125**
Data: **14.10.2021**
Documento materiale: **4959075477**

Creato da: **ANGEGAGL***Destinatario***LCN Automotive Equipment, S.A.
Avda. Cristobal Colon, 304
19004 GUADALAJARA
SPAGNA**

Partita iva:

*Luogo di destinazione***LCN Automotive Equipment, S.A.
Avda. Cristobal Colon, 304
19004 GUADALAJARA
SPAGNA**

Partita iva:

541	UM da mag. a forn.LE	Trasporto a mezzo vettore
------------	-----------------------------	----------------------------------

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	1	PZ	2510088401	Meccanismo attuaz. ruota	0,825	KG

Aspetto		Nota		
CARTONE		I.R. 2-113669 DHL 4123317925		
Colli	Peso lordo	Tipo trasporto	ID Trasporto	Incotermis
1 PZ	1,200 KG			
Vettore		Data e ora del ritiro		Firme
DHL EXPRESS		18.10.2021 09:46:28		
				Conducente
				Destinatario

AEOF: n. autorizzazione IT AEOF 17 1352

BAL 963841379



Quality Inspection Report

Inspection report No.: 20000113669
Receipt No.: 5010563770
Deliver note: 20A-111162

Date of inspection: 08.10.2021
Date of reception: 01.08.2020

Supplier	Quality Contact
LCN Automotive Equipment, S.A. Avda. Cristobal Colon, 304 19004 Guadalajara Spain	Name: Phone: E-Mail:

Material	Delivery Qty:	2640
Material-No.: 2510088401 Description: Actuation Mechanism cpl	Tax ID number:	ESA19227230

Preliminary information for Supplier:
While inspecting your delivery we have identified the below mentioned quality demerits. We would like to request you to take according containment actions and to avoid repetitive failures in future. In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

1 CARTONE
1,2 kg
30 x 20 x 20 cm

Failure description: Park Lock Actuation Mechanism Not OK
Quality Notification Origin: Customer complain EKD

Quantity Affected: 1 Part
Complain number: 78063
DATA MATRIX: 20073091024138024141A2510088401?h
Transmission serial number: 10283822
Production date: 02/09/2010
Vers. 251/17.06-007
Customer: MERCEDES DCT300

Containment Actions must be implemented and reported to MagnaPT Bari Incoming Inspection in written form within 24 hours. MagnaPT STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.

We expect a written response within 24h concerning your immediate containment actions.
Please send your containment actions in form of a 8D report to following email: getrag_hotline.supplier@magna.com
Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity:	1
Redelivered quantity:	1

Best regards

[Handwritten signature]

Magna PT S.p.A. a socio unico Via dei Ciclamini 4 I-70026 Modugno (Bari) Tel. 080 - 5 85 81 11 Fax. 080 - 5 85 82 04 Subject to the activity of the direction and coordination of Magna Powertrain GmbH	Cap.Soc.: EUR 25.850.000,00 i.v.R.Imprese di Bari C.F. e P.IVA 04886850728 REA 339886 www.magna.com	EUR: BNL-Banca Nazionale del Lavoro SpA IBAN code EUR: IT94 V010 0504 0000 0000 0007 855 BIC code: BNLITRR 6560 12 USD: Bank of America N.A. IBAN code USD: GB64 BOFA 1650 5071 1710 20 BIC code: BOFAGB22
---	---	---





Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA_CONSALVO@MAGNA.COM

Destinatario

LCN MECANICA SL
//
AVDA CRISTOBAL COLON 304
POL_IND "EL HENARES"

19004 GUADALAJARA
Spain
+34949750090

Dettagli Spedizione

Data Spedizione: 2021-10-18
Numero Spedizione: 4123317925
Tipo Servizio: EXPRESSWORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 1,20kg
Volumetrico: 2,40kg
Tassabile: 2,50kg
Valore assicurato:
Condizioni commerciali:

Info internazionali

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Wednesday, 20 Oct, 2021
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 963841579
Codice per oneri e tasse:
Charge Breakdown: --,-- EUR

Servizi speciali: Supplemento Carburante/
Emergency Situation

Info riferimento

Riferimento: I.R. 2-113669
Numero di ritiro:

Contenuto

SPAREPARTS

258700