⋀ MAGNA

Cedente

Magna PT C/O SVEVATRANS S.r.l.
Via dei Gerani, 5
I-70026 MODUGNO

Partita iva: IT04886850728

Numero:	50000956
Data:	09.09.2021
Documento materiale:	5011480313
Ordine di acquisto:	5500044648
Creato da:	NICOMIGL

Destinatario

Luzhou Changjiang Machinery Co
No. 18, Section 4, JiuGU Road,
646000 LUZHOU SICHUAN
CINA

Partita iva:

Luogo di destinazione

Luzhou Changjiang Machinery Co
No. 18, Section 4, JiuGU Road,
646000 LUZHOU SICHUAN
CINA

Partita iva:

922 EM ord. acq. Storno	Trasporto a mezzo vettore

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	395	PZ	2517170300	Supporto frizione	269,785	KG

Aspetto		Nota			
PALLET		I.R. 2-112169			
Colli 2 PZ	**Peso lordo** 269,785 KG	**Tipo trasporto**	**ID Trasporto**		**Incoterms** EXW
Vettore		Data e ora del ritiro		Firme	
		10.09.2021 08:27:01			
				Conducente	
				Destinatario	

Supplier	Advanced information for the supplier		
Luzhou Changjiang Machinery Co.Ltd **No. 18, Section 4, JiuGU Road, Jian** **646000 LUZHOU SICHUAN** **CINA**	Inspection Report No./ created: 200000112169 / 06.05.2021		
	Goods receipt No.:	5011222868	
	Delivery No.:	2021098	
	Goods receipt Date:	29.04.2021	
	Lot no.:	000000000000	
	Part description		Part-No.
	Clutch Support		**2517170300**
	Quantity:	**2.520**	VAT No.: IT04886850728

During inspection of the above mentioned parts we found the below listed defects. We expect you to take correctiv actions to prevent such problems in the future. Another inspection report will be issued in case of further defects found on the same parts.

The payment of the goods after discovering the deficiencies by GETRAG is not considered as an acknowledgement of the goods as duly.

You are requested to send a written response (8D-Report) to department   until *11.05.2021*.

Defect description:

Damaged grooves
         ********Update 26.07.2021 + 657 parts.*******

Quality Notification Origin: Assembly line
Defect: Damaged grooves
Quantity: 02 parts

Containment Actions must be implemented and reported to Magna PT Bari Incoming Inspection in written form within 24 hours.

QN Origin:	II Incoming Inspection defect
Disturb Index:	3 3-Medium

Inspected quantity:	657
Return delivery quantity:	657

Quality contact person:		**Logistic contact person:**	
Tester:	Ruggiero Doronzo	Logistics:	
Telephone:		Telephone:	
E-Mail:	Ruggero.Doronzo@magna.com	E-Mail:	

Charges for the defective or rejected parts will be made seperately under the above mentioned number.
CONTROL PLAN HAS TO BE REVIEW? YES NO

   With best regards