



188732

Cedente

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996	
Numero:	40000383
Data:	12.02.2021
Documento materiale:	5011025361
Ordine di acquisto:	5500043774
Creato da:	F.CORTI

Destinatario

Magna PT
BURGBERNHEIMER STRASSE 5
D-91438 BAD WINDSHEIM
GERMANIA

Partita iva:

Luogo di destinazione

Magna PTB.V. & Co. KG
BURGBERNHEIMER STRASSE 5
D-91438 BAD WINDSHEIM
GERMANIA

Partita iva:

922	EM ord. acq. Storno	Trasporto a mezzo vettore
------------	----------------------------	----------------------------------

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	154	PZ	0550722445	Gruppo sincronizzazione 1	91,168	KG

Aspetto	PEDANA	Nota	I.R. 3-110657 DHL4975862124
---------	--------	------	-----------------------------

Colli	1 PZ	Peso lordo	133,000 KG	Tipo trasporto	ID Trasporto	Incoterms
-------	------	------------	------------	----------------	--------------	-----------

DHL EXPRESS	16.02.2021 10:20:39	
		Conducente
		Destinatario



Quality Inspection Report

Inspection report No.: 200000110657
 Receipt No.: 5010856634
 Deliver note: 0007234126

Date of inspection: 16.12.2020
 Date of reception: 23.11.2020

Supplier	Quality Contact
Magna PT B.V. & Co. KG (Att Andreas Meyer) Burgbernhelmer Straße 5 91438 Bad Windsheim Germany	Name: Phone: E-Mail:

Material	
Material-No.: 0550722445 Description: Hub System 1st/7th Gear cpl	Delivery Qty: 4200 Tax ID number: DE146126877

Preliminary information for Supplier:
 While inspecting your delivery we have identified the below mentioned quality demerits.
 We would like to request you to take according containment actions and to avoid repetitive failures in future.
 In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

1 PEDANA
 1 33 kg
 box 60 x 70 cm

Failure description: Internal MDK NOK
 ***** UP DATE 11/02/2021 *****
 Defect: Internal MDK Bigger
 Quantity: 154 pcs

Quality Notification Origin: Assembly line

Defect: Internal MDK Bigger (Info report)
 Quantity: 125 pcs

Info: We send the parts for your analysis

We expect a written response within 24h concerning your immediate containment actions.
 Please send your containment actions in form of a 8D report to following email: getrag.hotline.supplier@magna.com
 Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
 In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:	
Claimed quantity:	279
Redelivered quantity:	154

Best regards

0

5011025361

Magna PT S.p.A.
 a socio unico
 Via dei Ciclamini 4
 I-70026 Modugno (Bari)
 Tel. 080 - 5 85 81 11
 Fax. 080 - 5 85 82 04
 Subject to the activity of the direction
 and coordination of
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
 i.v.R. Imprese di Bari
 C.F. e P.IVA 04886850728
 REA 339886
 www.magna.com

EUR: BNL-Banca Nazionale del
 Lavoro SpA
 IBAN code EUR: IT94 V010 0504 0000
 0000 0007 855
 BIC code: BNLITRR 6560 12
 USD: Bank of America N.A.
 IBAN code USD: GB64 BOFA 1650
 5071 1710 20
 BIC code: BOFAGB22

Vedi abbonem-DHL



Inspection Report

Supplier Magna PT B.V. & Co. KG Burgberheimer Straße 5 D-91438 BAD WINDSHEIM GERMANIA	Advanced information from the supplier	
	Inspection Report No./ created:	200000111141 / 10.02.2021
	Goods receipt No.:	5010791465
	Delivery No.:	0007232416
	Goods receipt Date:	02.11.2020
	Lot no.:	00000000000
	Part description	Part-No.
	Clutch Cooling Pump	2510204509
	Quantity: 1.920	VAT No.: IT04886850728

During inspection of the above mentioned parts we found the below listed defects. We expect you to take correctiv actions to prevent such problems in the future. Another inspection report will be issued in case of further defects found on the same parts.

The payment of the goods after discovering the deficiencies by GETRAG is not considered as an acknowledgement of the goods as duly.

You are requested to send a written response (8D-Report) to department until 11.02.2021.

Defect description:

CCP nok
Quality Notification Origin: Customer complain EKD

Quantity Affected: 1 Part

DATA MATRIX:

DMC CCP:
20103091017854114945P2517204700?j
20102891017854104956A2517204802?e
DMC E-motor:
2008219102061550012662517255213?d

Transmission serial number: CSMA544
Production date: 03/12/2020
Vers. 251/4,10-001
Distance covered: Km 5
Vin Number: VF1RFE00X66568263
Customer: RENAULT DCT300

Containment Actions must be implemented and reported to MagnaPT Bari Incoming Inspection in written within 24 hours.

MagnaPT STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.

QN Origin: EKD Customer complaint

Disturb Index: 1 1-Very high

Inspected quantity: 1

Return delivery quantity: 1

Quality contact person on:

Tester: vitangelo SANTAMARIA
Telephone:
E-Mail: Vitangelo.Santamaria@magna.com

Logistic contact person on:

Logistics:
Telephone:
E-Mail:

Charges for the defective or rejected parts will be made seperately under the above mentioned number.

CONTROL PLAN HAS TO BE REVIEW? YES NO

1 CARTONE
1,5 kg
30x20x20 cm

CUSTOMER RETURN 0070

~~Seissenschmidt~~
adone trasporto Schrotter
4800004784
Mathies
Lausehke

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax 080 - 5 85 82 04

Cap.Soc.: EUR 25.850.000,00
i.v.R. Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del Lavoro SpA
IBAN code EUR: IT94 V010 0504 0000 0000 0007 855
BIC code: BNLITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650 5071 1710 20
BIC code: BOFAGB22

Soggetta ad attività di direzione e coordinamento di Magna Powertrain GmbH
Subject to the activity of the direction and coordination of Magna Powertrain GmbH

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

MAGNA PT
MR. KOEBERER
Burgberheimer Strasse 5

91438 Bad Windsheim Bayern
Germany
+4998414070

Dettagli Spedizione

Data Spedizione: 2021-02-16
Numero Spedizione: 4975862124
Tipo Servizio: EXPRESS WORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 2
Peso Totale: 134,50kg
Volumetrico: 69,60kg
Tassabile: 135,50kg
Valore assicurato:
Condizioni commerciali:

Info internazionali

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Monday, 22 Feb, 2021
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 952190338
Codice per oneri e tasse:
Charge Breakdown: --,-- EUR

Servizi speciali: Supplemento Carburante/
Over Weight Piece (peso)/
Emergency Situation

Info riferimento

Riferimento: I.R. 2-111141-110657
Numero di ritiro:

Contenuto

ricambi