



Luzhou Changjiang Machinery Co.Ltd

No. 18, Section 4, JiuGU Road, Jiangyang District
Luzhou sichuan 646000
Cina

Sold to Address

Luzhou Changjiang Machinery Co.Ltd

No. 18, Section 4, JiuGU Road, Jiangyang District
Luzhou sichuan 646000
Cina

188787

47	
21/12/2020	
Description	
Part Number	
2517170300	Clutch Support
1	
11	
11,00	
Gabinile Quirelli	
ir 2/110682	
21-dic-2020	
FATTURA VALIDA AI SOLI FINI DOGANALI	
Material not in compliance	
peso kg 0,8	
Totale Imponibile	
€EUR 11,00	
Imponibile	
Aliquota IVA	
Imposta	
0%	
0	
Totale Documento	
€EUR 11,00	

Spedizione del pacchetto

Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

LUZHOU XINGNENG CNG AUTOMOBILE
WANG JUN
N° 18 SECTION 4 JIUGU ROAD

646000 LUZHOU SICHUAN
China, Peoples Republic
+8618117953380

Dettagli Spedizione

Data Spedizione: 2021-01-05
Numero Spedizione: 5273829153
Tipo Servizio: EXPRESS WORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 0,80kg
Volumetrico: 0,40kg
Tassabile: 1,00kg
Valore assicurato:
Condizioni commerciali: DDP

Info internazionali

Valore dichiarato: 11,00 EUR
Codice per oneri e tasse: Shipper
Stato tassabile: Dutiable
Data di consegna stimata: Wednesday, 13 Jan, 2021
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 113812703
Codice per oneri e tasse: 113812703
Charge Breakdown: 54,15 EUR

Servizi speciali: Supplemento Carburante/Dazi
e Tasse Doganali Pagate/
Situazione di emergenza

Info riferimento

Riferimento:
Numero di ritiro:

i.r. 2-110682

Contenuto

ricambi

GEN. 2021

Mittente (Nome, reparto)		Roberto Posa Incoming Inspection (BWLQ4)	
Destinatario (Indirizzo, persona da contattare, telefono) Luguo di destinazione (se diverso dal destinatario)		Att.To (Mr.) Luzhou Changjiang Machinery Co.LTD. No.18 Section 4, Jiugu Road, Luzhou National HI-TECH zone,Sichuan,China. 646000, Luzhou Sichuan, China	
Spese di trasporto a carico di... > se a carico della Getrag S.p.A. è necessaria l'autorizzazione. > se a carico del destinatario è necessario che costui comunichi il trasportatore da utilizzare in porto assegnato		Franco ☐ (spese di trasporto a carico della Getrag S.p.A.) Assegnato ☐ (spese di trasporto a carico del destinatario); Trasportatore:	
		AUTORIZZATO dal DIRIGENTE di reparto <i>Robert o Posa</i>	
Contenuto	Tipo di imballaggio	Nr. colli	Denominazione merce
	cartone	1	Clutch Cone Ring
			0558730305
			504 Pz.
			80x60x46
			kg 103,6
			Ir 2'110136
Centro di costo: 730 Consegna gratuita ? Si ☐ No ☐ Ordine acquisto (da indicare in caso di vendita)			
Data massima di arrivo presso il destinatario: ☒ in 2 giorni ☐ in 4 giorni ☐ senza indicazioni			



Quality Inspection Report

Inspection report No.: 200000110196
Receipt No.: 5010790372
Deliver note: 2020196

Date of inspection: 04.11.2020
Date of reception: 31.10.2020

Supplier

Luzhou Changliang Machinery Co. Ltd
No. 18, Section 4, JINGGU Road, Jian
646000 Luzhou Sichuan
China

Quality Contact

Name: Cosimo Altavilla
Phone: 39060585858
E-Mail: Cosimo.Altavilla@magna.com

Material

Material-No.: 0558730305
Description: Clutch Cone Ring

Delivery Qty: 4860
Tax ID number:

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
We would like to request you to take according containment actions and to avoid repetitive failures in future.
In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

19.11.2020

Failure description: part not conform on Ø 52,64

UP DATE 14/12/20
Defect 2: Rust internal diameter -> Actual scraps: 502
Defect 3: Plane surface damage [Ø 70,5] -> Actual scraps: 4

Quality Notification Origin: Rejected from Assembly Line

Quantity Affected: 01 Parts (Partial result)

Defect 1: part not conform on Ø 52,64

Attached photo

Containment Actions must be implemented and reported to Magna Barf Incoming Inspection in written form within 24 hours.

Magna STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to

following email: getrag.hotline.supplier@magna.com

Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 507
Redelivered quantity: 1

Best regards

Cosimo Altavilla