

**DOCUMENTO DI TRASPORTO (D.d.t.)**

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

**Magna PT S.p.A.  
Via dei Ciclamini 4  
I-70026 MODUGNO**

Partita iva: IT04886850728

**Numero: 40001999  
Data: 15.09.2021  
Documento materiale: 5011490884  
Ordine di acquisto: 5500043698****Creato da: NICOMIGL**

Destinatario

**Linamar Hungary Zrt. PPM Divis  
Békéscsaba, Szarvasi út 86-88  
H-5600 HUNGARY**

Partita iva:

Luogo di destinazione

**Linamar Hungary Zrt. PPM Divis  
Békéscsaba, Szarvasi út 86-88  
H-5600 HUNGARY**

Partita iva:

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.	
922	EM ord. acq.	Storno		Trasporto a mezzo vettore			
001	1	PZ	2510650100	Chart Scatola differenza	3,790	KG	
Aspetto				Nota			
CARTONE				I.R. 2-113422 DHL9241481362			
Colli		Peso lordo		Tipo trasporto		ID Trasporto	Incoterms
1 PZ		4,200 KG					
Vettore				Data e ora del ritiro		Firme	
DHL EXPRESS				15.09.2021 11:59:15			
						Conducente	
						Destinatario	



# Quality Inspection Report

Inspection report No.: 20000113422  
 Receipt No.: 5011402878  
 Deliver note: 140430

Date of inspection: 14.09.2021  
 Date of reception: 19.07.2021

## Supplier

Linamar Hungary Zrt. PPM Division  
 Békéscsaba, Szarvasi út 86-88  
 5600 Hungary  
 Hungary

## Quality Contact

Name:  
 Phone:  
 E-Mail:

## Material

Material-No.: 2510650100  
 Description: GrpNo Differential Housing pre asm

Delivery Qty: 3360  
 Tax ID number: HU10732346

## Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.  
 We would like to request you to take according containment actions and to avoid repetitive failures in future.  
 In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

1 CARTONE

**Failure description:** shaft differential longer

Quality Notification Origin: Rejected from Assembly Line

Quantity Affected: 01 Part (Partial result)

Defect: 01 Differential Housing (part number 2510650100) with shaft differential longer than the drawing dimension, real value is 115.65mm and at drawing is 114.3-0.2mm

4,2 kg  
 30 x 20 x 20 cm

Containment Actions must be implemented and reported to MagnaPT Bari Incoming Inspection in written form within 24 hours. MagnaPT STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.

**We expect a written response within 24h concerning your immediate containment actions.**

Please send your containment actions in form of a 8D report to following email:

[getrag.hotline.supplier@magna.com](mailto:getrag.hotline.supplier@magna.com)

Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at [GETRAG.SMRT@magna.com](mailto:GETRAG.SMRT@magna.com)  
 In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

## Affected Quantity:

Claimed quantity: 1  
 Redelivered quantity: 1

Best regards

0

Magna PT S.p.A.  
 a socio unico  
 Via dei Ciclamini 4  
 I-70026 Modugno (Bari)  
 Tel. 080 - 5 85 81 11  
 Fax. 080 - 5 85 82 04  
 Subject to the activity of the direction  
 and coordination of  
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00  
 i.v.R. Imprese di Bari  
 C.F. e P.IVA 04886850728  
 REA 339886  
 www.magna.com

EUR: BNL-Banca Nazionale del Lavoro SpA  
 IBAN code EUR: IT94 V010 0504 0000 0000 0007 855  
 BIC code: BNLITRR 6560 12  
 USD: Bank of America N.A.  
 IBAN code USD: GB64 BOFA 1650 5071 1710 20  
 BIC code: BOFAGB22

Ref. 50M490884



# Ricevuta delle spedizioni

## Mittente

MAGNA PT  
MAGNA PT  
V. DEI CICLIAMINI 4 1

70026 MODUGNO  
Italy  
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

## Destinatario

LINAMAR HUNGARY ZRT. PPM DIVISION  
//  
Szarvasi ut 86-88

5600 Bekescsaba  
Hungary  
+3666450250

158563

## Dettagli Spedizione

Data Spedizione: 2021-09-15  
Numero Spedizione: 9241481362  
Tipo Servizio: EXPRESS WORLDWIDE  
Tipo Imballaggio: My Own Package  
Numero Colli: 1  
Peso Totale: 4,20kg  
Volumetrico: 2,40kg  
Tassabile: 4,50kg  
Valore assicurato:  
Condizioni commerciali:

## Info internazionali

Valore dichiarato:  
Codice per oneri e tasse:  
Stato tassabile: Non-Dutiabile  
Data di consegna stimata: Friday, 17 Sep, 2021  
Codice promozionale:

## Info di pagamento

Tipo pagamento: DHL Account Number  
Codice pagante: 113812703  
Codice per oneri e tasse:  
Charge Breakdown: 46,78 EUR

Servizi speciali: Supplemento Carburante/  
Emergency Situation

## Info riferimento

Riferimento: I.R. 2-113422  
Numero di ritiro:

## Contenuto

spare parts