MAGNA

DOCUMENTO DI TRASPORTO (D.d.t.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Numero:	**40001121**
Data:	**10.05.2021**
Documento materiale:	**5011249659**
Ordine di acquisto:	**5500043032**
Creato da:	N.MIGLIETTA

Cedente

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

Destinatario

Porite Yangzhou Tec. & Ind. Co
No.399 Hanjiang South Rd. Yang
225127 YANGZHOU CITY
CINA

Partita iva:

Luogo di destinazione

STANTE
VIA DEI GERANI 4
70026 MODUGNO

Partita iva:

268514

922 EM ord. acq. Storno	Trasporto a mezzo destinatario

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	48	PZ	2501243402	Ruota dentata doppia 01	5,904	KG

Aspetto: CARTONE		Nota: I.R. 2-111365		
Colli: 1 PZ	Peso lordo: 5,904 KG	Tipo trasporto	ID Trasporto	Incoterms
Vettore: **SVEVATRANS**		Data e ora del ritiro: 13.07.2021 11:37:49	Firme	
			Conducente	
			Destinatario	

GETRAG **Spedizione n.** Attendere info da ~~[illegible]~~ Miglietta

Data 03/05/2021

Mittente (Nome, reparto)	Posa Roberto ,B/WLQ
Destinatario (Indirizzo, persona da contattare, telefono) **Luogo di destinazione** (se diverso dal destinatario)	STANTE

Spese di trasporto a carico di...

- se a carico della Getrag S.p.A. è necessaria l'autorizzazione,
- se a carico del destinatario è necessario che costui comunichi il trasportatore da utilizzare in porto assegnato

Franco ☑
(spese di trasporto a carico della Getrag S.p.A.)
Assegnato ☒
(spese di trasporto a carico del destinatario);
Trasportatore: _____

AUTORIZZATO dal **DIRIGENTE** di reparto

Roberto Posa

(firma)

Contenuto

Tipo di imballaggio	*Nr. colli*	Denominazione merce	Codice materiale	Q.tà	Valore della merce *(Obbligatorio x la dogana o assicurazione)*	Peso *Kg.*	Causale del trasporto
Cartone	**01**	**2501243402**	**Ruota Dentata Doppia 01**	**48**	€	14	**Ir 2'111365**
~~**Cartone**~~	~~**01**~~	**2501243509**	**Ruota Dentata Doppia 01**	**50**	€		**Ir 2'112107**
~~**Cartone**~~	~~**01**~~	**2511104302**	**Ruota Dentata Doppia 01**	~~8~~ 7	€		**Ir 2'112108**
40x30x30 cm					€		

Centro di costo:	_____ **639** _____	**Consegna gratuita ?**	**Si** ☐ **No** ☐	**Ordine acquisto:** (da indicare in caso di vendita)	_____

Data massima di arrivo presso il destinatario:	☐ in 2 giorni ☐ in 4 giorni ☐ senza indicazioni
Termine periodo immagazzinamento richiesto **(nel caso.di merce inviata a magazzino esterno):**	_____

50M249659
50M249700
50M249706

Quality Inspection Report

MAGNA

Inspection report No.: **200000111365**
Receipt No.: **5011009960**
Deliver note: **1-210011-1**

Date of inspection: **24.02.2021**
Date of reception: **08.02.2021**

Supplier

Porite Yangzhou Tec. & Ind. Co., Lt
No.399 Hanjiang South Rd. Yangzhou
225127 Yangzhou City
China

Quality Contact

Name: Ruggiero Doronzo
Phone:
E-Mail: Ruggero.Doronzo@magna.com

Material

Material-No.: **2501243402**
Description: **Double Gear Wheel 01**

Delivery Qty: **15552**
Tax ID number:

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
We would like to request you to take according containment actions and to avaoid repetitive failures in future.
In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until **15.04.2021**

Failure description: Broken tooth
Quality Notification Origin: Self Announcement

Defect: Parts with broken tooth (ref. claim 200000111148 – 2511167813 – Broken tooth From Kechnec, Slovakia)
Quantity: 48

Containment Actions must be implemented and reported to Magna PT Bari Incoming Inspection in written form within 24 hours.
Magna STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.

We expect a written response within 24h concerning your immediate containment actions.
Please send your containment actions in form of a 8D report to
following email: getrag.hotline.supplier@magna.com
Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: **48**
Redelivered quantity: **48**

Best regards

Ruggiero Doronzo

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax. 080 - 5 85 82 04
Subject to the activity of the direction
and coordination of
Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
i.v.R.Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del Lavoro
SpA
IBAN code EUR: IT94 V010 0504 0000
0000 0007 855
BIC code: BNLIITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650
5071 1710 20
BIC code: BOFAGB22