MAGNA

DOCUMENTO DI TRASPORTO (D.d.t.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Numero:	40000468
Data:	07.03.2022
Documento materiale:	5011831910
Ordine di acquisto:	5500039990
Creato da:	FABICORT

Cedente

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

Destinatario

Magna PT B.V. & Co. KG
Hermann-Hagenmeyer-Strasse 1
D-74199 UNTERGRUPPENBACH
GERMANIA

Partita iva:

Luogo di destinazione

Magna PT B.V. & Co. KG
Hermann-Hagenmeyer-Strasse 1
D-74199 UNTERGRUPPENBACH
GERMANIA

Partita iva: 283883

922 EM ord. acq. Storno	Trasporto a mezzo destinatario

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	2	PZ	2506445335	Albero di uscita 1	3,940	KG

Aspetto: CARTONE		Nota: IR 2'115273		
Colli: 1 PZ	Peso lordo: 3,940 KG	Tipo trasporto	ID Trasporto	Incoterms: EXW
Vettore: **DHL EXPRESS AWB 4937705625**		Data e ora del ritiro: 17.03.2022 18:38:39	Firme	
			Conducente	
			Destinatario	

Quality Inspection Report

MAGNA

Inspection report No.: **200000115273**
Receipt No.: 5011777443
Deliver note: 0007263042

Date of inspection: 02.03.2022
Date of reception: 04.02.2022

Supplier

Magna PT B.V. & Co. KG
Hermann-Hagenmeyer-Strasse 1
74749 Rosenberg
Germany

Quality Contact

Name: Francesco Giovanniello
Phone:
E-Mail: Franco.Giovanniello@magna.com

Material

Material-No.: **2506445335**
Description: Output Shaft 1

Delivery Qty: 1280
Tax ID number: DE146126877

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
We would like to request you to take according containment actions and to avaoid repetitive failures in future.
In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until 02.03.2022

1 CARTONE
30x20x20 cm
4,3 Kg

Failure description: Missing working

Quality Notification Origin: Reject Line

Quantity Affected: 2 Part (Partial result)
Defect: Missing working (raw material on the surface near profile R)
Delivery Number: 7263042

We expect a written response within 24h concerning your immediate containment actions.
Please send your containment actions in form of a 8D report to
following email: getrag.hotline.supplier@magna.com
Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 2
Redelivered quantity: 2

Best regards

5011 831 910

Francesco Giovanniello

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax. 080 - 5 85 82 04
Subject to the activity of the direction
and coordination of
Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
i.v.R.Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del
Lavoro SpA
IBAN code EUR: IT94 V010 0504 0000
0000 0007 855
BIC code: BNLIITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650
5071 1710 20
BIC code: BOFAGB22