

**Cedente**

Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO

Partita iva: IT04886850728

DOCUMENTO DI TRASPORTO (D.T.H.)	
D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996	
Numero:	40000807
Data:	20.04.2022
Documento materiale:	4961707554
Creato da:	FABICORT

Destinatario

Nemak Spain, S.L.
Poligono Galarza S/N 1
48277 ETXEBARRIA
SPAGNA

Partita iva:

Luogo di destinazione

Nemak Spain, S.L.
Poligono Galarza S/N 1
48277 ETXEBARRIA
SPAGNA

Partita iva:

283765

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	1	PZ	2510317461	Scatola frizione com	10,418	KG

Aspetto		Nota		
CARTONE		I.R. 2-115470 DHL 4461457125		
Colli	Peso lordo	Tipo trasporto	ID Trasporto	Incoterms
1 PZ	12,300 KG			

DHL EXPRESS	20.04.2022 12:32:05	
		Conducente
		Destinatario



Spedizione n. 202007201V6YJ
Data 12/04/2022

Mittente (Nome, reparto)		Lucchese Tommaso Qualità, Bsq4					
Destinatario (Indirizzo, persona da contattare, telefono) <i>Empfänger (Adresse, Ansprechpartner, Telefon)</i>		Nemak Europe Poligono Galarza 1 Etxebarria Bizkaia 48277 España					
Spese di trasporto a carico di... - se a carico della Getrag S.p.A. è necessaria l'autorizzazione, - se a carico del destinatario è necessario che costui comunichi il trasportatore da utilizzare in porto assegnato		Franco (spese di trasporto a carico della Magna PT S.p.a.) ☐ Assegnato (spese di trasporto a carico del destinatario) ☒ DHL - 963845456					
Contenuto		AUTORIZZATO dal DIRIGENTE di reparto (firma)					
Tipologia di imballaggio	Nr. colli	Denominazione merce	Codice materiale	Q.tà	Valore della merce (Obbligatorio x la dogana o assicurazione)	Peso Kg.	Causale del trasporto
PARZONE	1	Clutch Housing	2510317461	01	€	12,31R.	2'115470
box box	10	box					
Centro di costo:							
Data massima di arrivo presso il destinatario: ☒ in 2 giorni ☐ in 4 giorni ☐ senza indicazioni							
Consegna gratuita ? ☐ Sì ☐ No ☐ Ordine acquisto (da indicare in caso di vendita)							

SI PREGA DI COMPILARE IL MODULO A STAMPATELLO, IN MODO CHIARO E LEGGIBILE

IN CASO DI INCOMPLETEZZA DI DATI NON SI DARA' SEGUITO ALLA SPEDIZIONE SENZA ALCUN PREAVVISO PER IL MITTENTE.

	Quality Inspection Report Inspection report No.: 200000115470 Receipt No.: 5010894648 Deliver note: 11426105	Date of inspection: 21.03.2022 Date of reception: 07.12.2020						
Supplier Nemak Spain, S.L. Poligono Galarza S/N 1 48277 Etxebarria Spain	Quality Contact Name: Cosimo Altavilla<INVALID> Phone: +390805858668 E-Mail: #Cosimo.Altavilla@magna.com							
Material Material-No.: 2510317461 Description: Clutch Housing cpl	Delivery Qty: 1200 Tax ID number: ESB48966154							
Preliminary information for Supplier: While inspecting your delivery we have identified the below mentioned quality demerits. We would like to request you to take according containment actions and to avoid repetitive failures in future. In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.								
The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.								
We expect your reply to this inspection report (e.g. 8D) addressed to below contact until 07.04.2022								
<table border="0" style="width: 100%;"> <tr> <td style="width: 30%; vertical-align: top;"> Failure description: Leakage Test cooling circuit-INFO REPORT Update 12/04/22 Quantity Affected: 01 Part Defect: Leakage Test of the cooling circuit DMC:0201023.91018520.083743P.2510317461#A </td> <td style="width: 70%; text-align: center; vertical-align: middle;"> S1 : 496 170755 S2 : 496 1707668 </td> </tr> </table> <table border="0" style="width: 100%;"> <tr> <td style="width: 30%; vertical-align: top;"> Quality Notification Origin: Customer Complain EKD (INFO REPORT) Quantity Affected: 01 Part Defect: Leakage Test of the cooling circuit DMC: 20071491018520053925A2510317460# Complain Number: 100000078426 VIN: WF02XXERK2LL67840 Transmission serial: 11880 KM: 7140 </td> <td style="width: 70%;"></td> </tr> </table> Containment Actions must be implemented and reported to Getrag Bari Incoming Inspection in written form within 24 hours. Magna STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.			Failure description: Leakage Test cooling circuit-INFO REPORT Update 12/04/22 Quantity Affected: 01 Part Defect: Leakage Test of the cooling circuit DMC:0201023.91018520.083743P.2510317461#A	S1 : 496 170755 S2 : 496 1707668	Quality Notification Origin: Customer Complain EKD (INFO REPORT) Quantity Affected: 01 Part Defect: Leakage Test of the cooling circuit DMC: 20071491018520053925A2510317460# Complain Number: 100000078426 VIN: WF02XXERK2LL67840 Transmission serial: 11880 KM: 7140			
Failure description: Leakage Test cooling circuit-INFO REPORT Update 12/04/22 Quantity Affected: 01 Part Defect: Leakage Test of the cooling circuit DMC:0201023.91018520.083743P.2510317461#A	S1 : 496 170755 S2 : 496 1707668							
Quality Notification Origin: Customer Complain EKD (INFO REPORT) Quantity Affected: 01 Part Defect: Leakage Test of the cooling circuit DMC: 20071491018520053925A2510317460# Complain Number: 100000078426 VIN: WF02XXERK2LL67840 Transmission serial: 11880 KM: 7140								
We expect a written response within 24h concerning your immediate containment actions. Please send your containment actions in form of a 8D report to following email: getrag.hotline.supplier@magna.com Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.								
Affected Quantity: <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Claimed quantity:</td> <td style="width: 10%; text-align: center;">1</td> <td style="width: 60%;"></td> </tr> <tr> <td>Redelivered quantity:</td> <td style="text-align: center;">1</td> <td></td> </tr> </table> Best regards Cosimo Altavilla<INVALID>			Claimed quantity:	1		Redelivered quantity:	1	
Claimed quantity:	1							
Redelivered quantity:	1							

Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

VIVIANA.CONSALVO@MAGNA.COM

Destinatario

NEMAK
//
POLIGONO GALARZA S/N 1
//

48277 ETXEBARRIA
Spain
+34946169000

Dettagli Spedizione

Data Spedizione: 2022-04-20
Numero Spedizione: 4461457125
Tipo Servizio: EXPRESS WORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 12,30kg
Volumetrico: 19,20kg
Tassabile: 19,50kg
Valore assicurato:
Condizioni commerciali:

Info internazionali

Valore dichiarato:
Codice per oneri e tasse:
Stato tassabile: Non-Dutiable
Data di consegna stimata: Friday, 22 Apr, 2022
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 963845456
Codice per oneri e tasse:
Charge Breakdown: --,-- EUR

Servizi speciali: Supplemento Carburante/
Emergency Situation

Info riferimento

Riferimento: I.R. 2-115470
Numero di ritiro:

Contenuto

spare parts