Gleason - PFAUTER

Gleason
Total Gear Solutions

PACKING LIST

Ship to: 2231
Magna PT S.p.A.
Via dei Ciclamini 4
70026 Modugno
Italy

Sold to: 2231
Magna PT S.p.A.
Via dei Ciclamini 4
70026 Modugno
Italy

Packing List No.: 800690613

GLEASON ORDER No.	SUPPLIER CODE	METHOD OF SHIPMENT	SHIP VIA
452035706	100907		Forw.Dachser

SHIPMENT TERMS 2010	SHIP DATE	CUSTOMER PURCHASE ORDER
DAP Modugno	04.11.2022	4500642892

ITEM No.	DESCRIPTION	QTY ORDERED	QTY DELIVERED	BALANCE DUE
0010	Gleason Material No.:GPM-DN-ZOM Repair of: Serial Number(s): (28671) Incl. Commodity Code: 84669360 Country of origin: DE 50132945 MAGNA Cod.For. 91000598 23 NOV. 2022 "Ricevuto con riserva e verifica" Firma Leggibile	1	1 30865	

CONTAINERS	SIZE	GROSS WEIGHT	NET WEIGHT	SHIPMENT No.
00001	80x60x54 cm	55 Kg	40 Kg	
	1 Pallet with frame			

Partner: Michelle Effenberger
Tel: 07141/404644
Fax: 07141/404555
Email: Meffenberger@Gleason.com

Gleason - PFAUTER

Gleason
Total Gear Solutions

PACKING LIST

Ship to: 2231
Magna PT S.p.A.
Via dei Ciclamini 4
70026 Modugno
Italy

Packing List No.: 800690613

GLEASON ORDER No.	SUPPLIER CODE	METHOD OF SHIPMENT	SHIP VIA
452035706	100907		Forw.Dachser

SHIPMENT TERMS 2010	SHIP DATE	CUSTOMER PURCHASE ORDER
DAP Modugno	04.11.2022	4500642892

ITEM No.	DESCRIPTION	QTY ORDERED	QTY DELIVERED	BALANCE DUE
0020	Customer Material No.: HYD-M00448 Gleason Material No.: 28365810 POWER CLAMPING CYLINDER HPL160/20 in our plant in Ludwigsburg. Following parts have been exchanged : 2x Block valve -26157750 1x Scraper -26147060 1x Stepseal -28277730 1x Quadring - 28277180 1x Ring -15369240 1x Stepseal -26158330 1x Scraper -26158000 1x Sealing -11816360 1x O-ring -3848530 2x Roller Bearing -15370640 Services - disassembly of unit - visual inspection - complete cleaning - change of a.m. spares - reassembly and test - preparation for dispatch Any old parts replaced during the repair / overhaul of the assembly, will immediately be scrapped at the time of return of the assembly. At your explicit request, we will arrange to return deliver the old parts back to you, provided you send us such request in writing prior completion of the repair / overhaul work. In the absence of such request, we assume your approval to the disposal / scrapping of the old parts. In case of non-commissioning, we reserve the right to charge you for the costs incurred as well as the transport costs for the return delivery of the unit. Warranty: 12 months on changed parts and performed service work.	1	1	

Gleason - PFAUTER

Gleason
Total Gear Solutions

PACKING LIST

Ship to: 2231
Magna PT S.p.A.
Via dei Ciclamini 4
70026 Modugno
Italy

Packing List No.: 800690613

GLEASON ORDER No.	SUPPLIER CODE	METHOD OF SHIPMENT	SHIP VIA
452035706	100907		Forw.Dachser

SHIPMENT TERMS 2010	SHIP DATE	CUSTOMER PURCHASE ORDER
DAP Modugno	04.11.2022	4500642892

ITEM No.	DESCRIPTION	QTY ORDERED	QTY DELIVERED	BALANCE DUE
	Commodity Code: 84122180 Country of origin: DE + + + +

Gleason - PFAUTER

Gleason
Total Gear Solutions

PACKING LIST

Ship to: 2231
Magna PT S.p.A.
Via dei Ciclamini 4
70026 Modugno
Italy

Packing List No.: 800690613

GLEASON ORDER No.	SUPPLIER CODE	METHOD OF SHIPMENT	SHIP VIA
452035706	100907		Forw.Dachser

SHIPMENT TERMS 2010	SHIP DATE	CUSTOMER PURCHASE ORDER
DAP Modugno	04.11.2022	4500642892

ITEM No.	DESCRIPTION	QTY ORDERED	QTY DELIVERED	BALANCE DUE
	our "Hotline" using following number: Spare Parts:+ 49-7141-4048012 VAT Number: IT04886850728			