

**DOCUMENTO DI TRASPORTO (D.d.t.)**

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

**Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO**

Partita iva: IT04886850728

**Numero: 40000504
Data: 27.02.2023
Documento materiale: 5012502374
Ordine di acquisto: 5500043698
Creato da: ANTOMOSC**

Destinatario

**Linamar Hungary Zrt. PPM Divis
Békéscsaba, Szarvasi út 86-88
H-5600 HUNGARY**

Partita iva:

Luogo di destinazione

**Linamar Hungary Zrt. PPM Divis
Békéscsaba, Szarvasi út 86-88
H-5600 HUNGARY**

Partita iva:

| Posizione | Quantità | U.M. | Codice materiale | Descrizione materiale | Peso netto | U.M. |
|----------------|--------------|------------|------------------|---------------------------|------------|--------------|
| 922 | EM ord. acq. | Storno | | Trasporto a mezzo vettore | | |
| 001 | 1 | PZ | 2510650100 | Chart Scatola differenza | 3,790 | KG |
| Aspetto | | | | Nota | | |
| CARTONE | | | | IR 2?118847 | | |
| Colli | | Peso lordo | | Tipo trasporto | | Incoterms |
| 1 PZ | | 3,790 KG | | | | EXW |
| Vettore | | | | Data e ora del ritiro | | Firme |
| DHL 1762771080 | | | | 27.02.2023 14:15:35 | | |
| | | | | | | Conducente |
| | | | | | | Destinatario |

32553



Quality Inspection Report

Inspection report No.: 200000118847
 Receipt No.: 5012448183
 Deliver note: 199443

Date of inspection: 15.02.2023
 Date of reception: 03.02.2023

Supplier

Linamar Hungary Zrt. PPM Division
Békéscsaba, Szarvasi út 86-88
5600 Hungary

Quality Contact

Name: Cosimo Altavilla
 Phone: _____
 E-Mail: Cosimo.Altavilla@magna.com

Material

Material-No.: 2510650100
 Description: GrpNo Differential Housing pre asm

Delivery Qty: 4896
 Tax ID number: HU10732346

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
 We would like to request you to take according containment actions and to avoid repetitive failures in future.
 In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until 28.02.2023

Failure description: Diameter 31.615 out of tolerance

Quality Notification Origin: Assembly Line

Quantity Affected: 01 part
 Defect: Diameter 31.615 out of tolerance
Real value 31.565

Attached measurement Zeiss + photo

Containment Actions must be implemented and reported to Magna Bari Incoming Inspection in written form within 24 hours.
 Magna STA expect a response (8D Report) for Root Cause and Corrective Action (s) within 14 days.

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to following email: getrag.hotline.supplier@magna.com
 Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
 In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 1
 Redelivered quantity: _____

Best regards-

3012502376

Cosimo Altavilla

Magna PT S.p.A.
 a socio unico
 Via dei Ciclamini 4
 I-70026 Modugno (Bari)
 Tel. 080 - 5 85 81 11
 Fax. 080 - 5 85 82 04
 Subject to the activity of the direction
 and coordination of
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
 i.v.R. Imprese di Bari
 C.F. e P.IVA 04886850728
 REA 339886
 www.magna.com

EUR: BNL-Banca Nazionale del
 Lavoro SpA
 IBAN code EUR: IT94 V010 0504 0000
 0000 0007 855
 BIC code: BNLITRR 6560 12
 USD: Bank of America N.A.
 IBAN code USD: GB64 BOFA 1650
 5071 1710 20
 BIC code: BOFAGB22

Hg 3 30 < 20 x 20

ECONOMY SELECT **ESU** 

2023.07.27 09:00:10 107350821
From: Magna PT S.p.A.
Santalugi Carlo
Via del Cisternino, 4

Origin:
BRI

70025 MODUGNO
Italy

To: Linamar Hungary Zrt.
Quality - Kállainé Bujdosó Andrea
Szarvasi ut 88-88.

Contact:
Quality - Kállainé Bujdosó Andrea

5600 Bekescsaba
Hungary

HU-BUD-BEK BSZ

Day Time


Ref: Jován György

Pcs/Shtpl Weight Piece
3,0/54,0 kg **3 / 3**

Contents: 11 pcs scrap



WAYBILL 17 6277 1080



(2L)HU5600+40000000



(J) JD01 4800 0107 2898 5330