




Ship to Address
Hella Electronics Mexico, S.A. de C.V. AV. Ing. Antonio Gutierrez Cortina #16
37980 San Jose Iturbide Messico

Sold to Address
Hella Electronics Mexico, S.A. de C.V. AV. Ing. Antonio Gutierrez Cortina #16
37980 San Jose Iturbide Messico

PRO-FORMA INVOICE					
n. - num.		13			
del - date		28/03/2023			
Through bank			Condizioni di pagamento Payment terms		
Codice articolo Code number	Diseño Part number	Quantità Quantity	Prezzo Unit Unit price	Importo totale Total value	
USD	25/02/2023 1,0553				
Ir 2/119397					
Material not in compliance					
peso Kg 0,200					
			Totale Imponibile USD 5,71		
Imponibile		Alliquota IVA Imposta 0%	Totale Documento		EUR 5,41

321465

Magna PT S.p.A. a socio unico • Via dei Ciclamini 4 • 70026 Modugno (Bari) • Italia
 Cap.s.l.v €25.850.000 • C.F. e P.IVA.IT 04886850728
 R.I. c/o C.C.I.A.A. Bari: 04886850728 • R.E.A. 339886
www.magna.com
 Soggetta ad attività di direzione e coordinamento di Magna Powertrain GmbH
 Subject to the activity of the direction and coordination of Magna Powertrain GmbH


MAGNA
 Magna PT S.p.A.
 Via dei Ciclamini, 4
 70026 MODUGNO (BA)
 C.F. e P. IVA 04886850728



Ricevuta delle spedizioni

Mittente

MAGNA PT
MAGNA PT
V. DEI CICLIAMINI 4 1

70026 MODUGNO
Italy
+390805858665

bbbs1@magna.com

Destinatario

HELLA AUTOMOTIVE MEXICO, SA DE CV
//
AV. ING. ANTONIO GUITIERRE NR 16
PARQUE OPCION

37980 CHINO-SAN JOSE ITURBIDE GUANAJUATO
Mexico
+524191988119

Dettagli Spedizione

Data Spedizione: 2023-03-28
Numero Spedizione: 1969106436
Tipo Servizio: EXPRESSWORLDWIDE
Tipo Imballaggio: My Own Package
Numero Colli: 1
Peso Totale: 0,20kg
Volumetrico: 0,40kg
Tassabile: 0,50kg
Valore assicurato:
Condizioni commerciali: DAP

Info internazionali

Valore dichiarato: 5,71 EUR
Codice per oneri e tasse: Receiver
Stato tassabile: Dutiable
Data di consegna stimata: Tuesday, 04 Apr, 2023
Codice promozionale:

Info di pagamento

Tipo pagamento: DHL Account Number
Codice pagante: 960522899
Codice per oneri e tasse: Receiver Will Pay
Charge Breakdown: 45,23 EUR

Servizi speciali: Supplemento Carburante/WY/
Duties and Taxes Unpaid/
Emergency Situation

Info riferimento

Riferimento: INSPECTION REPORT 2/119397 ANT
Numero di ritiro:

Contenuto

TRANSMISSION RANGE SENSOR

<p>Supplier</p> <p>Hella Electronics Mexico, S.A. de C AV. Ing. Antonio Gutierrez Cortina 37980 SAN JOSE ITURBIDE-PARQUE OPCION MESSICO</p>	<p>Advanced information for the supplier</p> <p>Inspection Report No./ created: 200000119397 / 23.03.2023 Goods receipt No.: 5012509141 Delivery No.: 81193369 Goods receipt Date: 01.03.2023 Lot no.: 000000000000</p> <table border="1"> <tr> <td>Part description</td> <td>Part-No.</td> </tr> <tr> <td>Transmission Range Sensor</td> <td>2517256800</td> </tr> <tr> <td>Quantity: 17.280</td> <td>VAT No.: IT04886850728</td> </tr> </table>	Part description	Part-No.	Transmission Range Sensor	2517256800	Quantity: 17.280	VAT No.: IT04886850728		
Part description	Part-No.								
Transmission Range Sensor	2517256800								
Quantity: 17.280	VAT No.: IT04886850728								
<p>During inspection of the above mentioned parts we found the below listed defects. We expect you to take correctiv actions to prevent such problems in the future. Another inspection report will be issued in case of further defects found on the same parts.</p>									
<p>The payment of the goods after discovering the deficiencies by GETRAG is not considered as an acknowledgement of the goods as duly.</p>									
<p>You are requested to send a written response (8D-Report) to department until 24.03.2023.</p>									
<p>Defect description:</p> <p>Deep analysis request Quality Notification Origin: Customer Complaint (Field) Version: 251/9.09-002 Vin Number: WF0JXXGAHJNT26680 Transmission serial: 85312 KM: 0 --> Plant</p> <p>Q1=100000078901</p> <p>Part Number: 2517256800 Quantity Affected: 1 Part (Partial result)</p> <p>Defect: Deep analysis request Note: Amomalous sensor behavior, request depth analysis</p> <p>DATA MATRIX: 211110_91019938_B922200_2517256800_c QN Origin: EKD Customer complaint Disturb Index: 1 1-Very high</p>									
<p>Inspected quantity: 1 Return delivery quantity: 1</p>									
<table border="0"> <tr> <td>Quality contact person:</td> <td>Logistic contact person:</td> </tr> <tr> <td>Tester:</td> <td>Logistics:</td> </tr> <tr> <td>Telephone:</td> <td>Telephone:</td> </tr> <tr> <td>E-Mail:</td> <td>E-Mail:</td> </tr> </table>		Quality contact person:	Logistic contact person:	Tester:	Logistics:	Telephone:	Telephone:	E-Mail:	E-Mail:
Quality contact person:	Logistic contact person:								
Tester:	Logistics:								
Telephone:	Telephone:								
E-Mail:	E-Mail:								
<p>Charges for the defective or rejected parts will be made seperately under the above mentioned number. CONTROL PLAN HAS TO BE REVIEW? YES NO</p> <p>With best regards</p> <p>_____</p>									

Magna PT S.p.A.
a socio unico
Via dei Ciclamini 4
I-70026 Modugno (Bari)
Tel. 080 - 5 85 81 11
Fax 080 - 5 85 82 04

Cap.Soc.: EUR 25.850.000,00
i.v.R.Imprese di Bari
C.F. e P.IVA 04886850728
REA 339886
www.magna.com

EUR: BNL-Banca Nazionale del Lavoro SpA
IBAN code EUR: IT94 V010 0504 0000 0000 0007 855
BIC code: BNLIITRR 6560 12
USD: Bank of America N.A.
IBAN code USD: GB64 BOFA 1650 5071 1710 20
BIC code: BOFAGB22

Soggetta ad attività di direzione e coordinamento di Magna Powertrain GmbH
Subject to the activity of the direction and coordination of Magna Powertrain GmbH