

**DOCUMENTO DI TRASPORTO (D.d.t.)**

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

**Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO**

Partita iva: IT04886850728

**Numero: 40000503
Data: 27.02.2023
Documento materiale: 5012502372
Ordine di acquisto: 5500043698
Creato da: ANTOMOSC**

Destinatario

**Linamar Hungary Zrt. PPM Divis
Békéscsaba, Szarvasi út 86-88
H-5600 HUNGARY**

Partita iva:

Luogo di destinazione

**Linamar Hungary Zrt. PPM Divis
Békéscsaba, Szarvasi út 86-88
H-5600 HUNGARY**

Partita iva:

922 EM ord. acq. Storno				Trasporto a mezzo vettore			
Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.	
001	1	PZ	2510650100	Chart Scatola differenza	3,790	KG	
Aspetto				Nota			
CARTONE				IR 2'118881			
Colli		Peso lordo		Tipo trasporto		Incoterns	
1 PZ		3,790 KG				EXW	
Vettore				Data e ora del ritiro		Firme	
DHL WAYBILL 1762771080				27.02.2023 14:18:42			
						Conducente	
						Destinatario	

32553



Quality Inspection Report

Inspection report No.: 200000118881
 Receipt No.: 5012462932
 Deliver note: 200399

Date of inspection: 17.02.2023
 Date of reception: 09.02.2023

Supplier

Linamar Hungary Zrt. PPM Division
Békéscsaba, Szarvasi út 86-88
5600 Hungary
Hungary

Quality Contact

Name: Francesco Giovanniello
 Phone: _____
 E-Mail: Franco.Giovanniello@magna.com

Material

Material-No.: 2510650100
 Description: GrpNo Differential Housing pre asm

Delivery Qty: 4896
 Tax ID number: HU10732346

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
 We would like to request you to take according containment actions and to avoid repetitive failures in future.
 In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

Failure description: Missing of thread on all holes

Quality Notification Origin: Assembly Line

Quantity Affected: 01 part
 Defect: Missing of thread on all holes

Dmc: 230124_91025584_021718P_2510609800
 Dmc: P172584/0952

Handwritten: 3, 30620, 20

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to following email: getrag.hotline.supplier@magna.com
 Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com
 In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 1
 Redelivered quantity: 1

Best regards

Handwritten: 5012502372

Francesco Giovanniello

Magna PT S.p.A.
 a socio unico
 Via dei Ciclamini 4
 I-70026 Modugno (Bari)
 Tel. 080 - 5 85 81 11
 Fax. 080 - 5 85 82 04
 Subject to the activity of the direction
 and coordination of
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
 I.v.R. Imprese di Bari
 C.F. e P.IVA 04886850728
 REA 339886
 www.magna.com

EUR: BNL-Banca Nazionale del Lavoro
 SpA
 IBAN code EUR: IT94 V010 0504 0000
 0000 0007 855
 BIC code: BNLITRR 6560 12
 USD: Bank of America N.A.
 IBAN code USD: GB64 BOFA 1650
 5071 1710 20
 BIC code: BOFAGB22

ECONOMY SELECT **ESU** **DHL**

2023-02-27 MYDHL* 1 0 / *35-0021*
From: Magna PT S.p.A.
Gianluigi Cato
Via dei Colaninzi, 4
Origin: **BRI**

70028 MODUGNO
Italy
To: Linamar Hungary Zrt.
Quality - Kállainé Bujdosó Andrea
Szarvasi ut 86-88.
Contact
Quality - Kállainé Bujdosó Andrea

5600 Bekescsaba
Hungary

HU-BUD-BEK BSZ
Day Time

Ref: Jován György
Pcs/Ship Weight Piece
3,0/54,0 kg 2 / 3

Contents: 11 pcs scrap

WAYBILL 17 6277 1080


(2L)HU5600+40000000


(J) JD01 4600 0107 2896 5329